

**CHAIN DRIVE RATIOS**

Chain Source	Sprocket Teeth		Chain Ratio
	Drive	Driven	
OEM	65	65	1.00
Travao (Caspro)	65	57	1.14
Dunn (NLA)	65	55	1.18
Lambke ???>>	65	54	1.20

**FINAL DRIVE RATIOS**

FD Source	Pinion	Ring	FD Ratio
	Gear	Gear	
OEM Eldo (68-72)	14	43	3.07
OEM Eldo (73-78)	15	41	2.73
OEM GMC	14	43	3.07
OEM Toro (66-67)	14	45	3.21
OEM Eldo (67)	14	45	3.21
Cinnabar	12	41	3.42
Marvin Peck	13	45	3.46
Applied GMC	11	39	3.55
Applied GMC	10	37	3.70
Applied GMC	10	41	4.10

**OVERALL RATIOS**

FD Ratio	Chain Ratio			
	1	1.14	1.18	1.2
2.73	2.73	3.12	3.23	3.28
3.07	3.07	3.50	3.62	3.69
3.21	3.21	3.66	3.79	3.85
3.42	3.42	3.90	4.03	4.10
3.46	3.46	3.94	4.08	4.15
3.55	3.55	4.04	4.18	4.25
3.70	3.70	4.22	4.37	4.44
4.10	4.10	4.67	4.84	4.92

Source for most information:

<http://gmcmotorhome.info/front.html#RATIO>